

The listed McMaster part number, (9001K32), for the u-channel is incorrect. The correct part number is 9001K44 and the channel is 1/8" thick with a 1/2" base and 3/4" legs.